AUTHORITY FOR EXPENDITURE AFE NUMBER WORKSHEET X KAISER GYPSUM CO. KAISER CEMENT & GYPSUM CORP. PERMANENTE STEAMSHIP CO. APPR. DIV SERIAL GLACIER SAND & GRAVEL CO. PERMANENTE TRUCKING CO. SEATTLE WASHINGTON ISSUE AUTHORITY FOR ASSET ACQUISITION IS REQUESTED AS FOLLOWS: ESTIMATED COST AND USE SPENDING PLAN ITEM QUANTITY **DESCRIPTION AND TERMS** IN-SERVICE PERIOD TOTAL NO. AMOUNT MO. COST OF USE DATE 1 8,000 gallon Lignosite Storage Tank 7//7 3,225. 9503-011-3_ \$ 3,225.

JUSTIFICATION FOR ACQUISITION	(See Attached)			
(REFERENCE BY ITEM NUMBER)	,			
AMOUNT AND EXPLANATION OF RELATED NON-CAPITAL EXPENSE	OLD TAME			2,57
STATEMENT OF GAIN OR LOSS ON RETIRED FACILITIES	Original Cost Property H- Estimated Recovery from Sale or S Estimated Demolition and Removal Book Value as of Estimated Gainar (Loss) on Retire	Expense	7/1962 - 26-1 5/33 5	\$\frac{2,500,00}{-0-} \$\leq \leq \leq \leq \leq \leq \leq \leq
MAKE GOOD REPORT REQUIRED? (Circle) YES NO BY WHOM?			·	VHEN?
AUTHORIZATIONS		ACCOUNTING USE ONLY		

DEPRECIATION POLICY METHOD OF FINANCING (FOR CONTROLLER'S USE ONLY) CAPITALIZE EXPENSE INV.CR.APPL 020-02 P. J. Franklin YES YES YES NO 80 метноб Purchase X Division Au GUIDELINE CLASS # Lease Renewal FORM 27-A REV 12-66

The sum of \$3,225 is requested to purchase and install a new lignosite storage tank.

The existing tank is a round, wood stave, field assembled tank which has been in service for approximately 9 years. The tank has developed leaks in the seams and is showing signs of rot. Tank is difficult to clean due to possible collapse of the bottom and some of the side staves.

It is proposed to replace the existing wood tank with a Fiberglass storage tank with a capacity of 8,000 gallons.